

Michelle Lujan Grisham Governor

Howie C. Morales
Lt. Governor

NEW MEXICO ENVIRONMENT DEPARTMENT

Harold Runnels Building
1190 Saint Francis Drive, PO Box 5469
Santa Fe, NM 87502-5469
Telephone (505) 827-2855
www.env.nm.gov



James C. Kenney
Cabinet Secretary

Jennifer J. Pruett
Deputy Secretary

Certified Mail - Return Receipt Requested

March 15, 2019

Mr. Tom French French Brothers Inc 1010 Zuni Drive Alamogordo, NM 88310

Re: French Brothers Inc/Sonoma Ranch East Phase 9; CGP; SIC 1521; NPDES Compliance Evaluation Inspection; NPDES #NMU001984; February 13, 2019

Dear Mr. French:

Enclosed please find a copy of the report for the referenced inspection that the New Mexico Environment Department (NMED) conducted at your facility on behalf of the U.S. Environmental Protection Agency (USEPA). This inspection report will be sent to the USEPA in Dallas for their review. These inspections are used by USEPA to determine compliance with the National Pollutant Discharge Elimination System (NPDES) permitting program in accordance with requirements of the federal Clean Water Act.

You are encouraged to review the inspection report, required to correct any problems noted during the inspection, and advised to modify your operational and/or administrative procedures, as appropriate. If you have comments on or concerns with the basis for the findings in the NMED inspection report, please contact us (see the address below) in writing within 30 days from the date of this letter. Further, you are encouraged to notify in writing both the USEPA and NMED regarding modifications and compliance schedules at the addresses below:

Robert Houston
US Environmental Protection Agency, Suite 1200
Enforcement Branch (6EN-WS)
1445 Ross Avenue
Dallas, Texas 75202-2733

Sarah Holcomb, Program Manager New Mexico Environment Department Surface Water Quality Bureau Point Source Regulation Section P.O. Box 5469 Santa Fe, New Mexico 87502 If you have any questions about this inspection report, please contact Jennifer Foote at (505)827-0596 or at Jennifer.Foote@state.nm.us.

Sincerely,

/s/ Sarah Holcomb

Sarah Holcomb Surface Water Quality Bureau

Cc: Carol Peters-Wagnon, USEPA (6EN-WM) by e-mail David Long, USEPA (6EN-WM) by e-mail Amy Andrews, USEPA (6EN-WM) by e-mail David Esparza, USEPA (6EN-WM) by e-mail Robert Houston, USEPA (6EN-WS) by e-mail Darlene Whitten-Hill, USEPA (6EN-WC) by e-mail Nancy Williams, USEPA (6EN-WC) by e-mail Mike Kesler, NMED District III by e-mail Jakob Kidd, City of Las Cruces by email Rudy Chanez, French Brothers by email

Form Approved OMB No. 2040-0003 Approval Expires 7-31-85



NPDES Compliance Inspection Report									
Section A: National Data System Coding									
Transaction Code									
C O N S T R U C T I O N					5		A C R E S		
Inspection Work Days Facility Evaluation Rating BI QA Reserved 67 69 70 3 71 N 72 N 73 74 75 1							Reserved		
				Section 1	B: Fac	cility I	Data		
POTV	e and Location of Facility Inspected (I V name and NPDES permit number)	For inc	lustrial users dischargi	ng to POTW, also) includ	de	Entry Time /Date 2-13-19 8:30am		Permit Effective Date 2/16/2017
	na Ranch East Phase 9, Azure Hills and Prado del Sol						Exit Time/Date		Permit Expiration Date
Las C	ruces, NM 88011						2-13-19 5:00 pm		2/16/2022
	Ana County e(s) of On-Site Representative(s)/Titlet	(a)/Db	one and Fay Number(s	`				Oth	er Facility Data
None	- · · · · · · · · · · · · · · · · · · ·	(8)/ F110	one and Fax Number(s	,				Oui	er Facility Data
Name, Address of Responsible Official/Title/Phone and Fax Number Tom French/Owner French Brothers Inc 1010 Zuni Drive Alamogordo, NM 88310 SIC 1521 General Contractors-Single Family Houses Family Houses 32.3574°N, 106.7202°E						nily Houses			
				tion C: Areas Ev			rring Inspection sfactory, N = Not Evaluated)		
U	Permit	N	Flow Measurement	<u>,,,,,,,,, </u>	N			N	CSO/SSO
N	Records/Reports	N	Self-Monitoring Pa	ogram	N	Slu	ıdge Handling/Disposal	N	Pollution Prevention
N	Facility Site Review	N	Compliance Schedu	ıles	N	Pr	retreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory		M	Sto	orm Water	N	Other:
			Section D: Summary	of Findings/Con	ıments	s (Atta	ach additional sheets if necessary)		
 Inspector arrived on site at 02/13/2019 at approximately 8:30 am, the inspector contacted Mr. Elias Nieto, French Brothers Site superintendent by phone at 12:45pm. An onsite meeting could not be arranged for that day, the purpose of the inspection and preliminary findings were discussed by phone. See attached report for further explanations. 									
Name(s) and Signature(s) of Inspector(s)				Agency/Office/Telephone/Fax					Date 3-6-19
Jennifer Foote /s/ Jennifer Foote N			NMED/SWQB 505-827-0596						
Signature of Management QA Reviewer			Agency/Office/Phone and Fax Numbers				Date		
Sarah Holcomb, Program Manager /s/ Sarah Holcomb			NMED/SWQB 505-827-2798				3-13-19		

French Brothers Inc Sonoma Ranch East Phase 9 Compliance Evaluation Inspection February 13, 2019 NPDES Permit No. NMU0001984 Further Explanations

Introduction:

On February 13, 2019, a Compliance Evaluation Inspection (CEI) was conducted by Jennifer Foote of the State of New Mexico Environment Department (NMED), Surface Water Quality Bureau (SWQB), accompanied by Jacob Kidd and Peter Bennett, both of City of Las Cruces, at the Sonoma Ranch East Phase 9 Project. This inspection was in response to a complaint and the purpose of this inspection was to document the facility's status regarding the National Pollutant Discharge Elimination System (NPDES) permit requirements for stormwater discharges associated with industrial activity under 40 Code of Federal Regulations (CFR) 122.26 and U.S. Environmental Protection Agency (USEPA) Stormwater Construction General Permit (CGP). Storm water from this site discharges into the Las Cruces MS4. This site discharges stormwater to South Fork Las Cruces Arroyo and thence to Rio Grande in Segment 20.6.4.101 of the State of New Mexico Standards for Interstate and Intrastate Surface Waters, New Mexico Administrative Code (NMAC).

The NMED performs a certain number of inspections for the U.S. Environmental Protection Agency (USEPA), Region VI, under the NPDES permit program, in accordance with the federal Clean Water Act. USEPA uses these inspections to determine compliance with the NPDES permit program. This inspection report is based on information provided by the permittee's representatives, observations made by NMED staff, and records and reports kept by the permittee and/or NMED.

Observations Summary:

The project is the construction of residential homes in Las Cruces NM. There are multiple phases and builders in the general area. Sonoma Ranch LLC (NMR1000NV) and Caliper Construction (NMR1000NX) previously had permit coverage for this area under the 2017 CGP. French Brothers Inc, a current owner/operator of several individual lots within the greater plan of development has not applied for permit coverage as of the date of the inspection. The previous SWPPP prepared for the project area did not include information on how NPDES permit responsibility would be transferred to developers.

Two signs were found windblown in an arroyo to the north of the site (photo 1). There are signs of concrete and stucco washout directly on the ground on lots with a French Brothers sign (photo 2). In general, the practice in the area for BMPs is a 6 month tackifier application and a berm around the lot. Several berms on lots with French Brothers signs had not been maintained and had eroded through, allowing runoff to leave the home sites.

Inspection Findings:

Section 301 (a) of the Federal Water Pollution Control Act states that "Except as in compliance with this section and sections 302, 306, 307, 318, 402 and 404 of this Act, the discharge of any pollutant by any person shall be unlawful."

Per 40 CFR Part 122.26, storm water discharges associated with construction activity are required to obtain coverage under an NPDES permit. Large construction activity is defined in 40 CFR Part 122.26(b)(14)(x), as follows: "Construction activity including clearing, grading and excavation, except operations that result in the disturbance of less than five acres of total land area. Construction activity also includes the disturbance

of less than five acres of total land area that is part of a larger common plan of development or sale if the larger common plan will ultimately disturb five acres or more."

In addition, beginning on March 10, 2003, storm water discharges associated with small construction activity became regulated according to 40 CFR Part 122.26(b)(15)(i) for "[c]onstruction activities including clearing, grading and excavating that result in land disturbance of equal to or greater than one acre and less than five acres. Small construction activity also includes the disturbance of less than one acre of total land area that is part of a larger common plan of development or sale if the larger common plan will ultimately disturb equal to or greater than one acre and less than five acres."

40 Code of Federal Regulations Part 122.21(a) Duty to apply (1) states "Any person who discharges or proposes to discharge pollutants ...must submit a complete application to the Director in accordance with this section and part 124 of this chapter.".

According to the facility's representative and based on a review of the EPA storm water permit database, it has been determined that this owner/operator did not have NPDES construction general storm water permit coverage on the date of this inspection.

NMED/SWQB Official Photograph Log Photo # 1					
Photographer: Jennifer Foote	Date: 2/13/19	Time: 8:57 am			
City/County: Las Cruces/Dona Ana		State: New Mexico			
Location: Sonoma Ranch East Phase 9					
Subject: Windblown debris in drainage channel to north of site					



NMED/SWQB Official Photograph Log						
Photo # 2						
Photographer: Jennifer Foote	Date: 2/13/19	Time: 4:48pm				
City/County: Las Cruces/Dona Ana		State: New Mexico				
Location: Sonoma Ranch East Phase 9						
Subject: unmaintained berm with sediment in the gutter						



NMED/SWQB Official Photograph Log Photo # 3						
Photographer: Jennifer Foote	Date: 2/13/19	Time: 4:48 pm				
City/County: Las Cruces/Dona Ana		State: New Mexico				
Location: Sonoma Ranch East Phase 9						
Subject: construction entrance with concrete washout in the distance						



NMED/SWQB Official Photograph Log Photo # 4					
Photographer: Jennifer Foote	Date: 2/13/19	Time: 4:51 pm			
City/County: Las Cruces/Dona Ana		State: New Mexico			
Location: Sonoma Ranch East Phase 9					
Subject: Eroded berm with concrete washout, unmaintained silt fence on adjacent lot					

